

Oil Field Environmental Incident Summary

Incident: 20150306115259 **Date/Time of Notice:** 03/06/2015 11:52

Responsible Party: SAMSON RESOURCES COMPANY

Well Operator: SAMSON RESOURCES COMPANY

Well Name: CHRISTIANSON SWD 1

Field Name: BLOOMING PRAIRIE

Well File #: 90141

Date Incident: 3/5/2015 **Time Incident:** 09:30

Facility ID Number:

County: DIVIDE

Twp: 162

Rng: 98

Sec: 5

Qtr:

Location Description:

Submitted By: Cooper Hearne

Received By:

Contact Person: Brad Rogers
2 W 2ND ST SAMSON PLAZA
TULSA, OK 74103-3101

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	2.5	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk.

Areal Extent:

Potential Environmental Impacts:

No likely impacts.

Action Taken or Planned:

The faulty plug was replaced with a solid stainless steel plug.

Wastes Disposal Location: Water was placed into produced water tanks on location and any soils removed from location will be taken to an approved disposal facility.

Agencies Involved:

Updates

Date: 3/6/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.